


DETERMINATION OF LUMINOUS INTENSITY
BY AVERAGING METHOD

- (8) Measurements shall not be made where shadows are cast by roof control posts, ventilation equipment, or other obstructions necessary to insure safe mining conditions.
- (9) Where machine-mounted light fixtures are used on equipment, except self advancing roof support systems, measurements shall not be made of surfaces on or within 1 foot of a self-propelled machine.
- (c) For the purpose of making illumination measurements, an authorized representative of the Secretary may require the installation of temporary roof supports or the removal of the equipment to a similar working place in which permanent roof supports have been installed.
- (d) Light measuring instruments shall be properly calibrated and maintained. Instruments shall be calibrated against standards traceable to the National Bureau of Standards and color corrected to the Commission Internationale de l'Eclairage (CIE) Spectral Luminous Curve. The CIE Spectral Luminous Curve is as follows:



[41 FR 43534, Oct. 1, 1976]

## § 75.1719-4 Mining machines, cap lamps; requirements.

- (a) Paint used on exterior surfaces of mining machines shall have a minimum reflectance of 30 percent, except cab interiors and other surfaces which might adversely affect visibility.
- (b) When stationary light fixtures are used, red reflectors mounted in protective frames or reflecting tape shall be installed on each end of mining machines, except that continuous mining machines, loaders, and cutters need only have such reflectors or tape on the outby end. Reflectors or reflecting tape shall have an area of not less than 10 square inches.
- (c) Each person who goes underground shall be required to wear an approved personal cap lamp or an equivalent portable light.
- (d) Each person who goes underground shall be required to wear a hard hat or hard cap which shall have a minimum of 6 square inches of reflecting tape or equivalent paint or material on each side and back.

[41 FR 43534, Oct. 1, 1976]

## § 75.1720 Protective clothing; requirements.

On and after the effective date of this §75.1720 each miner regularly employed in the active workings of an underground coal mine shall be required to

wear the following protective clothing and devices:

- (a) Protective clothing or equipment and face-shields or goggles when welding, cutting, or working with molten metal or when other hazards to the eyes exist from flying particles.
- (b) Suitable protective clothing to cover those parts of the body exposed to injury when handling corrosive or toxic substances or other materials which might cause injury to the skin.
- (c) Protective gloves when handling materials or performing work which might cause injury to the hands; however, gloves shall not be worn where they would create a greater hazard by becoming entangled in the moving parts of equipment.
- (d) A suitable hard hat or hard cap. If a hard hat or hard cap is painted, non-metallic based paint shall be used.
  - (e) Suitable protective footwear.

[36 FR 19497, Oct. 7, 1971, as amended at 39 FR 7175. Feb. 25, 1974]

## § 75.1720-1 Distinctively colored hard hats, or hard caps; identification for newly employed, inexperienced miners.

Hard hats or hard caps distinctively different in color from those worn by experienced miners shall be worn by each newly employed, inexperienced miner for at least one year from the date of his initial employment as a miner or until he has been qualified or certified as a miner by the State in which he is employed.

[39 FR 7175, Feb. 25, 1974]

## § 75.1721 Opening of new underground coal mines, or reopening and reactivating of abandoned or deactivated coal mines, notification by the operator; requirements.

(a) Each operator of a new underground coal mine, and a mine which has been abandoned or deactivated and is to be reopened or reactivated, shall prior to opening, reopening or reactivating the mine notify the Coal Mine Health and Safety District Manager for the district in which the mine is located of the approximate date of the proposed or actual opening of such mine. Thereafter, and as soon as practicable, the operator of such mine shall submit all preliminary plans in accord-

ance with paragraphs (b) and (c) of this section to the District Manager and the operator shall not develop any part of the coalbed in such mine unless and until all preliminary plans have been approved.

- (b) The preliminary plans required to be submitted by the operator to the District Manager shall be in writing and shall contain the following:
- (1) The name and location of the proposed mine and the Mine Safety and Health Administration mine identification number, if known;
- (2) The name and address of the mine operator(s);
- (3) The name and address of the principal official designated by the operator as the person who is in charge of health and safety at the mine;
- (4) The identification and approximate height of the coalbed to be developed;
- (5) The system of mining to be employed;
- (6) A proposed roof control plan containing the information specified in §75.220.
- (7) A proposed mine ventilation plan containing the information specified in §§ 75.371 and 75.372;
- (8) A proposed plan for sealing worked-out areas containing the information specified in §§ 75.371 and 75.372.
- (9) A proposed program for searching miners for smoking materials in accordance with the provisions of §75.1702; and,
- (10) A proposed plan for emergency medical assistance and emergency communication in accordance with the provisions of §§ 75.1713–1 and 75.1713–2.
- (c) The preliminary plans required to be submitted by the operator to the District Manager shall be in writing and shall contain the following:
- (1) The proposed training plan containing the information specified in §§ 48.3 and 48.23 of this chapter, and
- (2) A proposed plan for training and retraining certified and qualified persons containing the information specified in §75.160-1.

[44 FR 9380, Feb. 13, 1979, as amended at 47 FR 23641, May 28, 1982; 57 FR 20929, May 15, 1992]